

Installation

Prior to installing your Komax Gamma 333, check the following points:

- **Floor:** Even, solid surface free of vibration
- **Does the floor have sufficient loading capacity?**
Machine weighs approx. 840 kg; with two mci 711 crimp presses, approx. 1030Kg
- **Avoid rooms with high humidity!**
- **Ambient temperatures should be neither too high nor too low.**
- **Power Connection:** 3x208-480V, N, PE; 50-60Hz 6kVA
5x4mm²; 25A fuse
- **Compressed air supply:** 4-6 bar
- **Space required for basic machine?**



Attention: Heed the connected load!



The machine may be operated only if it has a connected ground conductor.

Gamma 333 Installation

